


GET - Flagging on Mobile and Web Portal

Flagging on Mobile

1. Creating Flags in the Inspection:



- a. Flags are added during the inspection process on the **Measurement Points screen**.
2. Tap on an **Observation Point** to add a flag to that point as clicking on that point will make u edit the point which will make you add a flag to that exct point **Using the Flag Icon**:
 - a. Locate the **Flag Icon** in the menu.
 - b. **Click the Flag Icon** to add a flag.
 - i. The **Flag Icon will turn red** to indicate an active flag.
 - ii. If the **Flag Icon is black**, it means no flag is active, or the flag has been removed.
3. **Syncing Flags to the Web Portal**:
 - a. After adding flags during the inspection, **sync the inspection** to ensure the flags are uploaded to the Web Portal.
 - b. Look for a successful sync confirmation to verify the process is complete.

Flagging on the Web Portal

1. Accessing Inspection Details:

- a. Navigate to the **Inspection Details Page** for the implement or asset you are reviewing.
To go there search for this implement on your GET Dashboard once found you will see

flags added when doing a mobile inspection click on that flag to access the inspection details page

Search

Select Customer: BMA

Select Job Site: Maggie

Select Asset Type

Asset Make

Select Family

Select Make

Select Model

Select Serial Number

Select Asset/System Type

Select Component Type

Asset Serial Number

Asset Alt. Number

Evaluation: A B C X

On Equipment Inventory Template All

Reset Search

ASSET VIEW ASSET LOCATION HISTORY CRACK VIEW

Worn(%)	Customer	Job Site	Make	Type	Serial Number	Alt.Serial	Imp.Budget	Life	Residual	Total Life	Replace Date	Status	Warranty Status	Build No	Next Inspect	Last Inspect	Flag
64%	BMA	Maggie	MAINETEC	Hulk PC5500 6 Tooth	JBTest5500T6		12000	1544	456	2000	04 Jan 2025	On Equip -HEX1107	hours\0days		30 Dec 2024	15 Nov 2024	
76%	BMA	Maggie	MAINETEC	Hulk PC5500 6 Tooth	Bucket056		8000	2440	741	3181	17 Oct 2024	On Equip -HEX056			01 Dec 2024	17 Oct 2024	
86%	BMA	Maggie	CATERPILLAR	9800 Hulk 5 Tooth BucketV1	OKEZE9.99Bucket		0	2	0	2	04 Oct 2024	Inventory - Ready to Use			-	04 Oct 2024	
70%	BMA	Maggie	MAINETEC	Hulk PC5500 6 Tooth	JB15.July24Test1		12000	-6500	0	-6500	10 Sep 2024	Inventory - Awaiting Repair			-	10 Sep 2024	
120%	BMA	Maggie	MAINETEC	Hulk PC5500 6 Tooth	E2E8.9_9_GET_v1		0	1800	0	1800	04 Sep 2024	On Equip -8.9_9_GET			17 Oct 2024	04 Sep 2024	

2. Adding Flags:

Select Schematic to add an observation point/Crack (Click on thumbnail)

Floor view.jpg Left Sidewall View.jpg Right Sidewall View.jpg

Component Type	Component	Part#	C/N/G	CMU	Residual	Observation Point	Type	Limit	Worn	Measurement	(Crack) Severity	Flag	Photo	Comment	Questions	Include
Hockey Stick Left				4544	0				0.00 %		Component Type comment for Report					
	Hockey stick left 1	W110501118	G	4544	-2544	HS Left 01	Normal	8 MM	0.00 %	Measurement						
	Hockey stick left 2	W110501118	G	4544	-2544	HS Left 02	Normal	8 MM	0.00 %	Measurement						
	Hockey stick left 3	W110501118	G	4544	-2544	HS Left 03	Normal	8 MM	0.00 %	Measurement						
	Hockey stick left 4	W110501118	N	4544	-2544	HS Left 04	Normal	8 MM	0.00 %	Measurement						
	Hockey stick left 5	W110501118	N	4544	-2544	HS Left 05	Normal	8 MM	0.00 %	Measurement						
	Hockey stick left 6	W110501118	N	4544	-2544	HS Left 06	Normal	8 MM	0.00 %	Measurement						

- Locate the **Flag Icon** next to the Observation Point List.
- Click the **Flag Icon** to create a flag.
 - Additional options will allow you to **add images, comments, or any other necessary details** to the flagged issue.

3. Managing Flags:

- Clicking the **Flag Icon** toggles its status:
 - Red Flag Icon:** Indicates an active flag.
 - Black Flag Icon:** Indicates no active flag or a removed flag.